	•			
	•			
	U.S. Officials Only			
	CORPIDENTIAL			
	CENTRAL INTELLIGENCE AGENCY			
	INFORMATION REPORT	-	1.	
COUNTRY				50X1
SUBJECT		nd/		
	Steel Mill/Mechanical Department/Equipment/Security Measures/Parts Supplied by Other Factories			50X1
				30X1
		DATE DISTR.	1-54	
	INTE BUCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE.	NO. OF PAGES 4	:	
	OF THE UNITED STATES, SITHIN THE MEANING OF TITLE IS., SECTIONS 789 AND 784, OF THE U.S. CODE, AS AMENDED. ITS TRANSMISSION OR REVEL LATION OF ITS CONTENTS TO OR RECEIFT BY AN UNAUTHORIZED FERSON IS.	NO. OF ENCLS.	: .	
	THIS IS UNEVALUATED INFORMATION	SUPP. TO		
	THIS IS GREATED INFORMATION	REPORT NO.		50X1
		· · · · · · · · · · · · · · · · · ·		
1.	"The following information on the J Stalin steel works beginning of August 1953:	in labely dates up through	h the	
1.	"The following information on the J Stalin steel works beginning of August 1953:	in labely dates up through	n the	
1.	LOCATION "The J Stalin steel works are located north-west of 61 the settlement of Labedy and the workers' colony of 6 The plant is on the edge of the Kloinicki camei (Germann)	.iwice (German: Gleiwitz) be	trans	
	"The J Stalin steel works are located north-west of Cl the settlement of Labedy and the workers' colony of C The plant is on the edge of the Kloinicki canel (Gera Background "During World War II, this plant was greatly expended."	iwice (German: Gleiwitz) be zerwionka (German: Fotfeld) man: Adolf Hitler Kanal).	etween	
2.	LOCATION "The J Stalin steel works are located north-west of Cl the settlement of Labedy and the workers' colony of C The plant is on the edge of the Kloinicki canel (Gora Background "During World War II, this plant was greatly expanded department was added to the steel works, where casing guns, as well as bombs, were manufactured. During the	iwice (German: Gleiwitz) be zerwionka (German: Fotfeld) en: Adolf Hitler Kanal). At these time, a mechanica & for mines and heavy ertil	etween	
2. 3.	LOCATION "The J Stalin steel works are located north-west of 61 the settlement of Labedy and the workers' colony of 6 The plant is on the edge of the Kloinicki canel (Gera Background "During World War II, this plant was greatly expanded department was added to the steel works, where casing guns, as well as bombs, were manufactured. During the equipped with over 500 grinding machines.	awice (German: Gleiwitz) be bervionka (German: Fotfeld) an: Adolf Hither Kanal). At that time, a mechanical s for mines and heavy artill at perlow, this descriment	etween il lery was	
2. 3.	LOCATION "The J Stalin steel works are located north-west of Cl the settlement of Labedy and the workers' colony of C The plant is on the edge of the Kloinicki canel (Gora Background "During World War II, this plant was greatly expanded department was added to the steel works, where casing guns, as well as bombs, were manufactured. During the	nwice (German: Gleiwitz) be bervionka (German: Fotfeld) an: Adolf Hither Kanal). At ther time, a mechanical sofor mines and heavy extil at period; this descriment	etween). il lery was	
3·	LOCATION "The J Stalin steel works are located north-west of Cithe settlement of Labedy and the workers' colony of Cithe plant is on the edge of the Kloinicki canel (Germ Background) "During World War II, this plant was greatly expanded department was added to the steel works, where casing guns, as well as bombs, were manufactured. During the equipped with over 500 grinding machines. "The plant was only slightly damaged during the war bu occupied the area, almost the entire plant was dismensibilities blown up into the air. "After the Polish administration took over, the plant in order that it could manufacture hardware for the coprams for children, etc. In 1950, the complete remode for the purpose of transforming it into bolely a milligenterprise was given the name of 'J Stalin'. The med with entirely new machinery and the steel-production	awice (German: Gleiwitz) be zervionka (German: Fotfeld) en: Adolf Hitler Kanal). At there time, a mechanical for mines and heavy artill at period; this department tafter the Seviet units in their and a good part of the underwent partial resonatruensumer trede cuch sa metal alling of the plant was statennical department was some	llery was di culon beds, rted	
3·	LOCATION "The J Stalin steel works are located north-west of GI the settlement of Labedy and the workers' colony of G The plant is on the edge of the Kloinicki canel (Germ Background) "During World War II, this plant was greatly expanded, department was added to the steel works, where casing guns, as well as bombs, were manufactured. During the equipped with over 500 grinding machines. "The plant was only slightly damaged during the war bu occupied the area, almost the entire plant was dismensibilities blown up into the air. "After the Polish administration took over, the plant in order that it could manufacture hardware for the seprems for children, etc. In 1950, the complete remode for the purpose of transforming it into solely a millienterprise was given the name of 'J Stalin'. The men with entirely new machinery and the steel-production comes Martins ovens (Siemens-Martin Process?)	awice (German: Gleiwitz) be zervionka (German: Fotfeld) en: Adolf Hitler Kanal). At there time, a mechanical for mines and heavy artill at period; this department tafter the Seviet units in their and a good part of the underwent partial resonatruensumer trede cuch sa metal alling of the plant was statennical department was some	llery was di culon beds, rted	
3·	LOCATION "The J Stalin steel works are located north-west of GI the settlement of Labedy and the workers' colony of GI The plant is on the edge of the Kloinicki canel (Germ Background) "During World War II, this plant was greatly expanded, department was added to the steel works, where casing guns, as well as bombs, were manufactured. During the equipped with over 500 grinding machines. "The plant was only slightly damaged during the war but occupied the area, almost the entire plant was dismensibilities blown up into the air. "After the Polish administration took over, the plant in order that it could manufacture hardware for the express for children, etc. In 1950, the complete remode for the purpose of transforming it into colely a milligenterprise was given the name of 'J Stalin'. The med with entirely new machinery and the steel-production of some Martins ovens Siemens-Martin Process?	awice (German: Gleiwitz) be zervionka (German: Fotfeld) en: Adolf Hitler Kanal). At there time, a mechanical for mines and heavy artill at period; this department tafter the Seviet units in their and a good part of the underwent partial resonatruensumer trede cuch sa metal alling of the plant was statennical department was some	llery was di culon beds, rted	
3·	LOCATION "The J Stalin steel works are located north-west of GI the settlement of Labedy and the workers' colony of G The plant is on the edge of the Kloinicki canel (Germ Background) "During World War II, this plant was greatly expanded, department was added to the steel works, where casing guns, as well as bombs, were manufactured. During the equipped with over 500 grinding machines. "The plant was only slightly damaged during the war bu occupied the area, almost the entire plant was dismensibilities blown up into the air. "After the Polish administration took over, the plant in order that it could manufacture hardware for the seprems for children, etc. In 1950, the complete remode for the purpose of transforming it into solely a millienterprise was given the name of 'J Stalin'. The men with entirely new machinery and the steel-production comes Martins ovens (Siemens-Martin Process?)	awice (German: Gleiwitz) be zervionka (German: Fotfeld) en: Adolf Hitler Kanal). At there time, a mechanical for mines and heavy artill at period; this department tafter the Seviet units in their and a good part of the underwent partial resonatruensumer trede cuch sa metal alling of the plant was statennical department was some	llery was di culon beds, rted	
2. 3. 4. 5.	LOCATION "The J Stalin steel works are located north-west of Cithe settlement of Labedy and the workers' colony of Cithe plant is on the edge of the Kloinicki canel (Gera Background) "During World War II, this plant was greatly expanded department was added to the steel works, where casing guns, as well as bombs, were manufactured. During the equipped with over 500 grinding machines. "The plant was only slightly damaged during the war but occupied the area, almost the entire plant was dismensibilities blown up into the eir. "After the Polish administration took over, the plant in order that it could manufacture hardware for the express for children, etc. In 1950, the complete remode for the purpose of transforming it into colely a milligate was given the name of 'J Stalin'. The med with entirely new machinery and the steel-production of some Martins ovens Siemens-Martin Process?	derivorka (German: Gleiwitz) be berviorka (German: Fotfeld) an: Adolf Hitler Kanal). At that time, a mechanical for mines and heavy artill at perior, this department that are a good part of the underwent partial resonatrues and a good part of the underwent partial resonatrues and the plant was statistical department was equilepartment was sumplied with the properties of the properties o	llery was di culon beds, rted	

COM	IDENTIAL, U	S OF	FICIALS	OWLY
	the second second			

- 2 -

50X1-HUM

Main Divisions of Plant

6. "The plant is divided into two main parts:

a. Steel Mill: This section consists of 12 furnaces (of the Martins type), a number of electric ovens for hardening the steel and for the production of various kinds of steel; a rolling-plant (of the Robertson type), a foundry, and a modern rolling-plant for producing railway rails which was only established in 1953. This part of the plant occupies the southern end of the factory area. A huge scrap dump is located in this part right on the bank of the Klodnicki Canal.

With the exception of the section which produces various kinds of steel, the steel mill department mainly serves as an auxiliary plant for the Mechanical Department, which Department is now considered as having the most vital function of the entire enterprise.

b. Mechanical Department(Polish term: Zaklad Mechanicany): Since 1952, the mounting of Soviet-model tanks (T-34) has been performed in this Department. During the first period of operation, nearly all the parts to be mounted were imported. Now, quite a number of parts, except for motors and armament, are produced within the two main departments of the J Stelic plant.

The various sections of the Mechanical Department are housed in the following buildings:

1) On the left side of the main entrance gate is a barracks occupied by the secretary of the plant Communist cell. Also situated in this barracks are the plant trade union branch and an Industrial Police detachment. See No on the layout plan of the steel works

¹ 50X1-HUM

- 2) On the right side of the main entrance is a sever story uilding (wiezovicc) where the management and administration offices are located. See No 2 on the layout plan.
- 3) Close behind the management building as where the KBW guard unit has its offices. See No. 3 on the layout plany.
- 4) On proceeding farther into the Mechanical Department area, there is on the right side of the thoroughfare a large work-hall for mounting. The No. 4 on the layout plant. In this work-hall, which was completely rebuilt and equipped with machinery after 1951, the mounting of T-34 tacks is performed. Since last month /July 1953?, mounting of motorized armoved vehicles for artillery and 'Stalin-organs' /sic/ has also been performed here.

The machinery in this section is partly of the German type and partly of Polish make (produced at the Poreba machine-construction plant).

5) Behind this structure No. 47, a new work-hall had been added. See No. 5 on the layout plan7. In comparison to the other buildings in the factory yard, this new one is approximately 10 meters high and building an extremely modern style, with nearly all the walls being of glass.

the layout plan of the steel works is not absolutely accurate.

When drawing up the plan, it was impossible to check the proportions. Therefore, the distances between the buildings, the sizes of the buildings, etc, should not be taken as 100% exact. No plans of this factory are in existence except for the original blueprints prepared during its construction period.

Machinery has already been installed in this work-hall.

6-7) On the western side of the thoroughfare, another part of the Mechanical Department is now under organization. Between the northern and southern ends

CONFIDENTIAL/US OFFICIALS ONLY

50X1-HUM 50X1-HUM

50X1-HUM

50X1-HUM

Declassified in Part -	Sanitized Copy	Approved for Release 2013/03/08 : C	IA-RDP80-	-00809A000500290095-3
사람이 화용되어 됐다면서		CONFIDENTIAL/US OFFICIALS ONLY		

50X1-HUM

_ 3 .

of the yard, there is a special crane ('suwnice' type) for the unloading of premanufactured parts which arrive on the railway siding [No. 6 on the layout plen] to be mounted at the factory. Close to this installation, building ruins can be observed in their shambled condition [see No. 7].

8-9) Ferther south a new large modern work-hell is now under construction /see No. 8/. Still farther to the south, a smaller hall is being rebuilt and enlarged. One wing of this smaller hall is already occupied by a mechanical wirkshop, while the other wing is still under construction /see No. 2/.

10-11-12) Quite near these buildings /Nos. 8 & 2/ are three other buildings /see Nos. 10, 11 & 12/. In one building /No. 10/ is the section for steel-hardening. In the other two buildings /Nos. 11 & 12/ is the welding section.

13-14) The waste piles are dumped in the northern and western parts of the factory yard. Close to the railway siding and in the western part of the yard is a warehouse for semi-finished products which need further processing see No. 137. This warehouse is provided with a ramp. Close to this warehouse is the factory's laboratory building See No. 147.

7. "In the far southern part of the entire enterprise is the steel plant itself. This section starts with a group of new furnaces (of the Martine-type). See No. 15 on the layout plan. There are six furnaces in this group and they are the largest models in existence in Poland at the present time. Eighty tons of steel can be accommodated in one of these ovens at one time.

Security Measures

- 8. "The entire enterprise is surrounded by a stone wall with observation towers established at various points. The searchlights from these towers illuminate the whole factory area. The plant is not only guarded by the Industrial Police (which whole factory area. The plant is not only guarded by the Industrial Police (which type of protection is now customary in Poland) but also by a special KB detschment.


 Each employee is checked not only on entering the factory grounds but also when circulating between the various buildings within the factory compound. All employees and workers must always carry a special permission card indicating the specific department in which they are employed. To move between the various sections or Departments requires a special permission card stamped and approved by the KB office.
- 9. "In addition to the enlargement of the enterprise itself, the northern part of the Labedy Forest (Labender Forat) located east of the plant has been taken over by the Labedy Forest (Labender Forat) located east of the plant has been taken over by the steel works for the installation of a specially camouflaged tank 'warehouse'. Up steel works for the installation of a specially camouflaged tank 'warehouse'. Up to now /July 1953/, the tanks, after leaving the factory, were taken along the high-to now /July 1953/, the tanks, after leaving the factory, were taken along the high-to now /July 1953/, the tanks, after leaving the factory, were taken along the high-to now /July 1953/, the tanks, after leaving the factory, were taken along the high-to now /July 1953/, the tanks, after leaving the factory, were taken along the high-to now /July 1953/. The tanks after leaving the factory, were taken along the high-to now /July 1953/. The tanks after leaving the factory, were taken along the high-to now /July 1953/. The tanks after leaving the factory, were taken along the high-to now /July 1953/. The tanks after leaving the factory, were taken along the high-to now /July 1953/. The tanks after leaving the factory, were taken along the high-to-now /July 1953/. The tanks after leaving the factory were taken along the high-to-now /July 1953/. The tanks after leaving the factory were taken along the high-to-now /July 1953/.
- 10. "The part of the forest right behind the Gliwice public swimming-pool (called Kapielisko Lesne) has already been declared 'off limits' for the public. It is said that this popular sports-center in Gliwice will also be closed in the near future.

Parts Supplied by Other Factories

ll. "Among the main factories which supply parts for the J Stalin steel works is the Bierut steel plant in Czestochowa. This factory supplies tank plates (with special profiles). Another source of supply is the "tomil rubber plant in "orman, which produces the rubber balls needed on the wheels of tanks. There is also a steel mill in Silesia which makes the caterpillars for tanks.

50X1-HUM 50X1-HUM

CONFIDENTIAL/US OFFICIALS ONLY



Declassified in Part - Sanitized Copy Approved for Release 2013/03/08: CIA-RDP80-00809A000500290095-



